

K02 Hardware Kit Includes:

Pattern

Materials/Tools Required

Level Masking Tape Tape Measure

Recommended Cleaning Materials:

Lint Free Cloth or Wipes Clear Water in Spray Bottle Fantastik® All Purpose Heavy Duty Cleaner

Important: Wall surface must be clean and dry prior to adhering lettering. Allow paint to dry at least 72 hours.

Note:


The pattern shows the bottom of each letter. To assist you, the full letter is provided directly below.

Step 1

Dimensional Letters (Tape Mount)


K02

Tape pattern at desired location. Check for level using baseline (paper may be cut crooked). Tape to wall making sure pattern is free of wrinkles.




Step!

Remove VHB tape backers on letter.




Step 3:

Press letter to wall. Repeat Steps 2 and 3 for remaining letters.



Step 4:

Carefully remove pattern by pulling it down and away from letters.



Sten 5

Remove finger prints from letter faces and edges using recommended cleaning materials. DO NOT use ammonia or alcohol based cleaners.