

### K01 Hardware Kit Includes

Drill Point Pattern

### Materials/Tools Required

Level Masking Tape Tape Measure Drill with 3/16" bit Caulk Gun

GE RTV 108 or RTV 6700 Clear Silicone Adhesive \*

\*Available from Takeform

### Recommended Cleaning Materials:


Lint Free Cloth or Wipes Clear Water in Spray Bottle Fantastik® All Purpose Heavy Duty Cleaner Drop Cloth or Dust Pan

Important: Wall surface must be clean and dry prior to adhering lettering. Allow paint to dry at least 72 hours.

### Step 1


Dimensional Letters (Stud Mount)

Tape pattern at desired location. Check for level using baseline (paper may be cut crooked). Tape to wall making sure pattern is free of wrinkles.




## Step 2


Punch through center drill point symbol on pattern (holes are identified with a circle and a center mark). Leave bottom tapped and fold over. Drill 3/16" holes using template for reference as needed. Deburr holes in drywall.



### Step 3:


Finger tighten threaded studs into holes in back of each letter. Install nylon spacers (if applicable) on studs.






# Step 4:

Fill holes with silicone adhesive. Be careful not to over-apply silicone. Using too much may result in adhesive seeping from stud spacer when sign is pressed against wall.



## Step 5

Remove finger prints from letter faces and edges using recommended cleaning materials. DO NOT use ammonia or alcohol based cleaners.



9/21/16